



201 Grandin Road
Maineville, Ohio 45039
(513) 677-0500

Telephone Audio to BEAM Upgrade Overview

Overview of Installation

1. Replace the customer mic(s) and speaker(s), if provided.
2. Replace the customer base audio board(s).
3. Replace the Telephone Interface(s).
4. Connect the lane intercom cable.
5. Connect the Interface(s) to the buildings phone system with the cable(s) provided.
6. Test system operation.
7. Adjust audio levels as necessary, (See Adjusting the Audio Levels in the manual for the interface.)
8. Verify operation with store personnel.