
Replacement Autoveyor™ Motor


Manual

E. F. Bavis & Associates, Inc.

201 Grandin Road
Maineville, Ohio 45039
(513) 677-0500

HUB REMOVAL

REMOVE BOLTS FROM HOLE -A-
 THREAD INTO -B- AND PUSH HUB
 OFF OF THE PULLEY



Wiring Diagram

